

01 PREVIOUS STATE



A_BUS STOP
THE OLD FASHIONED STRUCTURE, ALSO DEGRADED, BROKE THE HARMONY OF THE SQUARE



B_ELECTRICAL AND PHONE WIRINGS
A HIGH NUMBER OF WIRINGS THAT INTERFERED WITH THE PANORAMIC VIEWS TO THE LAKE AND THE MOUNTAINS



C_ILLEGAL RAMP AND GARAGE
AN ILEGAL RAMP BUILT TO ACCESS TO A PRIVATE AND ALSO ILEGAL GARAGE IN A PROTECTED BUILDING



G_SLOPE NEAR THE CHURCH
THE REMAINS OF A FORMER LOADING DOCK FOR CATTLE COULD BE SEEN NEXT TO THE SLOPE CLOSE TO THE CHURCH, AS WELL AS A DEGRADED MASONRY WALL



H_DEAD TREES
DEAD TREE TRUNKS, AND ALSO TWO MORE OLD TREES CLOSE TO BE DRIED, LAID IN SOME POINTS



I_LINK WITH PLAZA CONSTITUCIÓN
THE SAME TYPE OF PAVEMENT ALREADY USED IN PLAZA CONSTITUCIÓN REDEVELOPMENT (2012), NEEDED TO BE CONTINUED



D_OLD SURFACE PARTIALLY COVERED
PARTS OF THE OLD GRANITE SURFACE NEAR THE NOBLE BUILDINGS ENTRANCE HAD BEEN COVERED



E_HUMIDITY
OCCASIONAL WATER ACCUMULATION IN A LOW POINT LED SMALL PALMS AND WEEDS GROWING IN ONE OF THE CORNERS



F_ILLEGAL PAVEMENTS
SOME NEIGHBORS BUILT ILLEGAL PAVEMENTS BREAKING THE SURFACE LEVEL OF THE SQUARE