$2. \ \ \text{TRANSFORMATION}. \ \ \text{BEFORE AND AFTER INTERVENTION}$ 



View from the south entry. Empty lot after the construction of the new residential building. Wall of the school and lighting poles delimiting the zone.



View from the school. Left: new housing unit. Back: commercial amenity. Centre: obtrusive electrical infrastructure.



View from the north entry corridor. Blind façades of the slabs and lighting barrier, no connection between school and plaza.





New floral lighting.



Free space for games.



Open playground at level with the plaza.



Colourful atmosphere.



Adapted plays.



New door and transparency between school patio and plaza.