02 PARTICIPATORY PROCESS FOR PUBLIC SPACE PRODAC NORTE

J216

With an aging population, the lack of accessibility conditions originated consecutive accidents, mostly due to poor pavement conditions and lack of handrails in most stairs. The same happened with children, who could not move freely due to the lack of security.
After winning the funding application and budgeting the proposed works, residents flocked to vote. The selected works were the improvement of accessibility conditions with the renovation of stairs, ramps and handrails; the consolidation and painting of walls; and the repaving and recovery of pavements.

- Repair and white color paint of the existing handrails with the application of a security net.
- Repair of the existing exterior stairs with anti-slip smoothing mortar in white color paint.
- Repair and white color paint of the existing exterior walls
- Repair
- White color paint
- Repair of the flowerbeds and sowing
- Construction of the acess for the beginning and end of the exterior stairs.